

2882753 K-ACCY,HEATER,ZS

The Ranger heater, 2882753 fuse issue update.

It has been determined that there was a batch of harnesses assembled incorrectly for the 2882753. If you run into an issue with the 2A fuse blowing, please compare the fuse block with either of the attached picture and if they are incorrect, please flip the fuses. This should fix the problem.

