

POLARIS

RACING

****Attention Polaris 2023 600 Cross Country Racers***

The taillight (#9 in below picture) bolts were not fully tightened down on the taillight assembly at the factory. Torque the taillight bolts to 16in-lbs.

