

# SEAT BELT ANCHOR FASTENER VERIFICATION INSTRUCTIONS

## INSPECTION LOCATIONS OVERVIEW


VIDEO INSTRUCTIONS

2023-2025 RANGER XP 1000 NorthStar / Crew XP 1000 NorthStar


<https://www.youtube.com/watch?v=PNuHfx77p1Q>



2023-2025 RANGER XP 1000 NORTHSTAR



2023-2025 RANGER CREW XP 1000 NORTHSTAR



## INSTRUCTIONS

1. Reference the following images. On the lower back of the seat area, locate where the seat belt anchor is attached to the frame. Inspect to make sure the fasteners have been tightened by checking that the fasteners are tight and **DO NOT** move when turned by hand.

### 2023-2025 RANGER XP 1000 NORTHSTAR / CREW XP 1000 NORTHSTAR FRONT SEAT



2. For multi passenger vehicles only, make sure the fasteners have been tightened by checking that the fasteners are tight and **DO NOT** move when turned by hand.

### 2023-2025 RANGER CREW XP 1000 NORTHSTAR REAR SEAT



3.

### STOP!

If any fasteners are found to not be tightened, you must stop operating the vehicle until repaired by an authorized Polaris dealer.

4. Continue to follow the Safety – Owner Requirements section of your owner's manual (including personal protective equipment, including helmet, and seat belt must be fastened). Failure to follow these instructions may lead to a risk of serious injury.

### IMPORTANT

Important: This inspection process is only meant to keep you riding safely prior to having the recall completed at your dealer. The safety recall will remain open on your VIN until a dealer completes the full inspection and as necessary repairs.